

Scope

Human Factors

- Airline flight operations
- Maintenance
- Aviation risk
- Regulatory approach
- · SMS
- A dynamic industry



Rule Development



Part 121 (large aeroplanes) – Crew member training & competency assessment

- Rule to be signed this week
- Human Factors training
- Flight crew and cabin crew
- All phases of training
- Instructor & Examiner competency (HF)
- 2 year transition

Rule Development

Part 125 (medium aeroplanes)

- Crew member training & competency assessment
 - Stalled; with MoT
 - Regulatory Impact Statement
 - o NPRM
 - Human Factors training (similar req'ts to Part 121)
 - Use of simulators
 - Line training safety



Advisory Circular

- Final draft completed
- Legal review completed
- Changes being incorporated (Rule alignment etc.)
- 2 year transition period (per Rule)
- Changes to crew member training approach
- Investment in instructor/examiner training
- Implementation guidance
- Joint industry regulator effort
- Need for further stakeholder engagement
 - Airline flight operations seminar 27 September 2012

Maintenance

 Part 145 Advisory Circular 'Human Factors in Maintenance' in development

Focus is to optimise safety performance and

reduce maintenance error

Considerable international guidance available

Some NZ Part 145
 organisations have
 HF programmes;
 industry input will
 be sought



CAA Organisational Changes

Appointment of Cabin Safety Inspector





 Developing capability in safety analysis unit (Human Factors specialist)

Aviation Risk

- Human Factors [breakdowns] have contributed to a large percentage of aircraft accidents
- Crew related HF risk factors include:
 - Lack of situational awareness (SA)
 - Poor decision making
 - Cognitive skills
 - Flight discipline / deviation from procedures
 - Low risk perception and/or high risk tolerance
 - Inadequate monitoring
 - Improper response to abnormal situations
- Recent accidents & incidents illustrate these human performance deficiencies still exist

Examples - Accidents

AF 447



Spanair 5022



- A brief stick shaker event occurred after take-off. At 400 ft the gear was noted as still being down and was raised. At 800 ft it was noted that the flaps were up, and had been inadvertently raised after take-off.
- On climb-out passing FL125 stick shaker activation and rapid speed decay upon entering edge of CB with associated turbulence. A/pilot disengaged and standard recovery accomplished.

- Pilot failed to set correct QNH on the subscale on descent. Aircraft had been instructed to descend to 8000 ft but came within 300 ft of aircraft maintaining 7000 ft.
- A flight crew member fell into a sudden deep sleep while on the flight deck due to fatigue

 At 200-300 ft on approach Rwy 23 wind gust generated IAS +20 kts increasing. Go-around carried out. Re-circuit visually for second attempt. Again at 200-300 ft wind gust with same result. Visual reposition over Lake Wakitipu in region of Jardines for approach to Rwy 05. Strong tailwinds at times but stable criteria met throughout for normal landing.

- During a transit walkaround the crew found the right hand engine left cowl latches undone. [The aircraft had an oil level check completed at previous departure point]
- A burning electrical smell was detected in the rear galley. On checking oven, it was noted that it was bright orange in colour and very hot. Oven was turned off for approximately one hour. Oven was turned on to facilitate continuation of meal service; within 5 -10min the oven fan and surround was orange again. The galley power was switched off and left off.

• ARC from pax (ATPL holder). Queenstown, moderate snow, visibility 1 mile, temp 0°. Aircraft taxied for take-off. Snow on wings and pax alerted cabin crew of need to de-ice. Concerns were dismissed. Pax then asked that flight crew be notified. FO inspected wings then Captain gave PA that they were going to continue as no de-icing fluid available. Pax talked to Purser and was adamant that aircraft should not take-off until de-iced, or he wanted off. Aircraft returned to gate. De-icing was completed. Aircraft departed.

Managing risk – operators/pilots


- Training
 - Technical and non-technical (HF/CRM) skills
 - Resilience



- Flight Discipline
 - Professionalism
 - Adherence to procedures
 - Rejecting shortcuts
 - Planning & preparation



Elements of good performance




CAA's Regulatory Approach

- Timeliness and responsiveness
- Impartiality, fairness, and consistency
- Risk-based, proportionate regulatory interventions
- Informed, analysis-led and evidence-based decisions
- Transparency and trust
- Constructive engagement with industry



Regulatory Operating Model



Regulatory response – considerations

| Event | Level of risk | Cause | Behaviour of participant | Public interest |
|--|-----------------------|---|---|--|
| Safety occurrence or breach Investigation | Low Medium High | Inadequate procedures Competency Threats not managed Errors not managed Procedure deviation At risk / careless Reckless | Reports event Accepts accountability No report Willing to learn Shifts blame Repeat event Cover-up Deception Deliberate | Risk identified and managed Systems improved Learning achieved Robust reporting Risk removed Held to account |

SMS Advisory Circular

- Accountability for safety
 - Responsibility vs. accountability
 - Important role of management
 - Safety culture
- Safety performance indicators
 - Reactive
 - Proactive / Predictive
 - Interactive



A Dynamic Industry

Risks







A Dynamic Industry

Technology







Final Thoughts



From a CAANZ perspective...

- Human performance continues to be a major factor in aviation accidents and serious incidents.
- Human Factors initiatives can be implemented now
- For industry participants, procedures, training (HF), and discipline are key initiatives to reduce risk
- Rules / guidance provided by regulator can assist
- CAANZ regulatory approach focused on reducing risk, promoting willing compliance with safety standards, and encouraging performance above the minimum standard
- Thank you for inviting our participation

